

EASYLINK MBX 5031152C001 30SEP85 08:59/09:14 EST  
VIA: 9108614125

TO: 62811461

EPA DAL

WU INFOMASTER 4-004634S273-002 09/30/85  
ICS IPMBNGZ CSP  
7137858152 DGM TDBN HOUSTON TX 139 09-30 0855A EST  
TWX 9108614125 EPA DAL  
1330 EPA

ATTN MARY ELLEN CROWLEY, OSC TXD 68510.332.7

POLRET #9 PCB SPILL BACH ELECTRICAL SERVICE INC RICHWOOD, BRAZORIA  
COUNTY TEXAS

SITUATION: ONE KNOWN HOT SPOT REMAINS IN THE DITCH AT FLAG #17.  
SAMPLE RESULTS ARE PENDING FOR SOIL SAMPLES TAKEN AT FLAG #12, #13,  
#18, #21. IF PCB CONCENTRATION EXCEEDS 50 PPM IN THESE AREAS,  
ADDITIONAL SOIL REMOVAL WILL BE NEEDED.

ACTION TAKEN: BILL LOONEY, ROLLINS PM, RECEIVED VERBAL RESULTS  
INDICATING THAT THE SAMPLES FROM FLAGS #12, #13, #18 AND #21 WERE  
UNDER THE 50 PPM ACTION LEVEL. APPROXIMATELY 6 INCHES OF SOIL WERE  
EXCAVATED AND REMOVED FROM THE DITCH AREA AROUND FLAG #17. A SOIL  
SAMPLE WAS TAKEN FROM THE EXCAVATED DITCH AREA TO ESTABLISH IF  
FURTHER EXCAVATION WILL BE REQUIRED.

FUTURE PLANS: FUTRE PLANS ON THIS SITE ARE PENDING SAMPLE RESULTS  
FROM THE DITCH AREA.

CASE PENDING REGION 6 DALLAS  
WARREN ZEHNER


0856 EST

EPA DAL

MMMM

YOUR MAILBOX IS NOW EMPTY  
EASYLINK

9316445A 30SEP85 09:15 EST  
PTS



90072477

